ART ZONE TUTORIAL 1 OF 9

Fill Outline

One click paints your whole part

Best for: Clean outlines, silhouettes and part templates

The art zone is where the AI puts the engraving art.
Paint it, and the Fabricator fills only that area.

reticle-red.com/fabricator

Fill Outline — One click paints your whole part



STEP 1 OF 5

Start on PAINT with your part loaded

This is the sample grip pair. The art zone is empty: nothing is painted yet.

RETICLE RED · ART ZONE TUTORIAL 1 OF 9

Fill Outline — One click paints your whole part



STEP 2 OF 5

Click FILL OUTLINE

It finds your part's shape and paints the whole inside. Free, no AI, no credits.

CLOSE-UP



Fill Outline — One click paints your whole part



STEP 3 OF 5

Holes stay clear

Screw holes and cut-outs are carved out automatically, so the art goes around them.

Fill Outline — One click paints your whole part



STEP 4 OF 5

Zone Edge: pull the art in from the edge

Drag ZONE EDGE to leave a border. The green ring shows the new edge while you drag.

Set it to 0 to run the art right to the edge.

CLOSE-UP



Fill Outline — One click paints your whole part



STEP 5 OF 5

Start over any time

CLEAR empties the zone. Ctrl+Z (Cmd+Z on a Mac) brings it straight back.

CLOSE-UP

